HABS NY 4-BING 26-

## HISTORIC AMERICAN BUILDINGS SURVEY

## INDEX TO PHOTOGRAPHS

HABS No. NY-5567

Delaware, Lackawana, & Western Railroad Station Lewis & Chenango Sts. Binghamton Broome County New York

Jack Boucher, Photographer, 1966

NY-5567-1 G	ENERAL VIEW	OF WEST	SIDE AND	SOUTH	FRONT,	SHOWING	TOWER
-------------	-------------	---------	----------	-------	--------	---------	-------

NY-5567-2 SOUTH FRONT (STREET SIDE) AND EAST SIDE

NY-5567-3 EAST AND NORTH (TRACK SIDE) SIDES

NY-5567-4 NORTH SIDE (TRACK SIDE)

NY-5567-5 INTERIOR OF WAITING ROOM, SHOWING TICKET WINDOW

Photocopies of photographs (ca. 1910, photographer unknown) courtesy of Erie Railroad Company.

NY-5567-6 GENERAL VIEW OF SOUTH FRONT, SHOWING TOWER

NY-5567-7 GENERAL VIEW OF WEST SIDE WITH STREET TROLLEY IN FOREGROUND